

SHIFT LEVER AND CONTROL CABLE COMPONENTS





INSPECTION OF SHIFT LEVER

MX03G - 02

INSPECT SHIFT LEVER PLAY

Check that there is no vertical play in the shift lever. If there is any play, replace bushing.

